

Fish Habitat Improvement Success Story



BEFORE

This project site is located on a tributary of the Lower Clearwater River. This photo was taken in 1992 prior to habitat improvement project implementation.

Habitat limitations at this site include high stream temperatures, lack of in-stream complexity, low summer flows, inadequate shelter, and sediment in stream.



Photo taken in 1995 after installation of habitat improvement projects. Improvements included installation of a livestock water system, grass seeding, fencing, tree planting, log drop structures, habitat rocks, and brush mattresses.



AFTER

June 2006—SUCCESS!!!

NEZ PERCE SOIL AND WATER
CONSERVATION DISTRICT

PO Box 131
Culdesac, Idaho 83524
208-843-2931